

FIG. 1

HELICOPTER NORMAL FLIGHT CONDITION




FIG. 2
BLADES RETRACTED

3/17




FIG. 3A




FIG. 3B









FIG. 4
BLADELETS DEPLOYED





6/17



7/17

Top View







DRIVE SHAFT IN MAST

FIG. 9

9/17




10/17



11/17

NOTE CHANGE TO 62
FROM PRIOR VERSION OF DRAWINGS



12/17






FIG. 13



14/17



15/17







FIG. 16



17/17

